

Kincardine O'Neil Auld Kirk Photographs

Photo 1: Deteriorated recent attempts of re-pointing using cement



Photo 2: Eroded pointing behind yew tree



Photo 3: Large area of eroded pointing behind yew tree



Photo 4: Deterioration of pointing around window on east gable



Photo 5: Deteriorated mortar in joints of granite buttress



Photo 6: Areas of eroded pointing on elevations



Photo 7: Lean on west gable of auld kirk

