



Ash Trees

Tree assessment ref -0194 noted tree (ASH 39) diseased and required monitoring. Badly damaged, at risk of full fall in stormy weather.

Tree assessment ref -0191 noted tree (ASH 35) diseased and required monitoring. Badly damaged, at risk of full fall in stormy weather.

Methodology:

1. Agreed MCU to cordon off area during storm warnings.
2. HES Works Manager to get contractors' method statement and costs for safe limb removal (this may not be possible given diseased condition of trees).
3. HES Works Manager to contact Cultural and Natural Resources (Bob Tevendale, Natural Heritage Advisor) to arrange for bat assessment.
4. Tree to be section felled to avoid damage to underlying archaeology.
4. Stumps to be cut to 100mm above ground level, and ground down to 100 mm below existing ground level.

# SMCP

Revisions:  
Rev. A 10/6/2016 Tree no 191 added.

MONUMENT	Palace of Holyroodhouse
PROJECT	Damaged Tree Removal Location Plan



PROJECT DRAWING NUMBER		2016-05-(90)-001A	
SCALE	1:200	ARCHITECT	Karen Willisamson
DATE	26/2/2016	DRAWN BY	John Crae
ARCHIVE NUMBER			