

Picture showing existing stone and concrete quadrants.




Picture showing typical Crinan Canal planned quadrants using granite setts.




Pictures showing collapsed wall at Lock 11 to be rebuilt like for like.





Lock 11 quadrants to be replaced.

Wall to be rebuilt.



Lock 11 Dunardry