



1. General view of garden area adjacent to west of Mill building before hedge was breached. The rubble wall and steps creating the gravelled viewing area terrace and estate railings are all 1980s or later in date.



11. View of garden area adjacent to west of Mill building showing breached hedge, damaged cherry tree and area where ground would be reprofiled under submitted proposals.