


General view on offside of bridge and original safety gate location



General view on bridge hole canal channel



Existing stop lank groves in concrete to remain



Poor masonry to be replaced & voiding filled