



Notes

Residual Risks

1. Add Text / There are no Residual Risks relating to these Works.
2. Add Text / Delete.
3. Add Text / Delete.

-  Indicates Area to be filled with weak mix Lime
-  Indicates Area to be filled with Turf/Grass Seed

Residual Risks

1. The precise weight of the two individual gate leaves is unknown but they are clearly of immense weight. The gate leaves cannot be dismantled in-situ, therefore they need to be removed and re-hung using a mechanical solution to be designed by the contractor under the terms of the contract.
2. There are live electrical cables which run below the existing deck level immediately below the gates.
3. The earlier layers of paint on the gates may be lead based.

Revisions

Contains Historic Environment Scotland, Ordnance Survey and Aerial Imagery Data
 © Historic Environment Scotland © Crown copyright and database rights 2016
 Ordnance Survey [100057073] © Getmapping

Ordnance Survey Data
 You are permitted to use this data solely to enable you to respond to, or interact with, the organisation that provided you with the data. You are not permitted to copy, sub-licence, distribute or sell any of this data to third parties in any form.

MONUMENT ELGIN CATHEDRAL
 PROJECT TOP DRESSING BELOW TABLE GRAVE STONES



PROJECT DRAWING NUMBER 459/142/1058
 SCALE NTS ARCHITECT M PENDERY
 DATE 10-08-16 DRAWN BY M JACK
 ARCHIVE NUMBER 459/142/1058