


Delta Bronze flat bar into joints to support broken lintol.

New Vertical Delta Bronze bar bedded into existing socket.

2no. new horizontal bars welded to vertical bar.

Front Elevation (1:10)



Plan (1:10)





Photo from inside if window showing socket.

New Vertical Delta Bronze bar bedded into existing sockets in sill and lintol.



Photo of sill showing socket.



Section (1:10)

SMC

MONUMENT	ST BRIDGETS KIRK
PROJECT	Window to South Elevation

HISTORIC ENVIRONMENT SCOTLAND | ÀRAINNEACHD EACHDRAIDHEIL ALBA

PROJECT DRAWING NUMBER		
SCALE	1:10 @ A3	ARCHITECT DMBorthwick
DATE	Jan '2017	DRAWN BY BTPringle
ARCHIVE NUMBER	365/266/076	

© Historic Environment Scotland - Scottish Charity No. SC045925