BRIAN MUNRO

SIDE VIEW



AERIAL VIEW



OUTLET OF 100MM PIPES TO BE OPEN ENDED AND HIDDEN BY ROUGH, ALLOWING WATER TO SEEP AND FILTER AWAY.
A HERRING BONE ENDED PIPE WOULD BE UNLIKELY TO WORK DUE TO MINIMAL DIG DEPTHS AND WOULD REQUIRE [illegible] EXCAVATIONS