contract ASHTM	job no 17.0323	prepared GM	date 27/2/20
South wall of Colours Room Pattress Detail.		checked	page SKC 54 B

david narro associates



Plan view on pattress detail

Where the dwang passes brick work it should continue to be fixed in to mortar joints only.



Section thro' pattress detail