Fig 3: location of proposed tests Every room downstairs and roof space: - thermal camera - snake camera All elements in roof space: - rubber hammer - mapping of visible decay/damage VSG: one frame every four in each roof Hygrometer: RILEM guidelines suggest 2 measurements for elements up to 2.5m in length, 3 measurements hygrometer for elements up to 4m in length, 4 measurements for elements above 4m in length - the guidelines will be followed unless part of the timbers are not 3 frames in each roof primary structural elements (=purlins) in northwest corner roof NB: the moisture content of additional timber elements will be measured if visible decay/damage or the hammer sounding suggest the presence of possible internal decay/damage -the <u>ultrasonic test</u> will be used to assess these same areas hygrometer hygrometer attic rooms hygrometer attic rooms