



Case information

Case ID	300018167
File Reference	HGH/B/TA/179
Name of Site	Burnmouth Bridge over Burn of Inchmill

Local Authority	Angus Council		
National Grid Reference	NO 32786 65753		
Designation No. (if any)	LB4814		
Designation Type	Listed Building	Current Category of Listing	B
Case Type	Amendment		

Received/Start Date	19/07/2016
Decision Date	25/08/2016

1. Decision

In our current state of knowledge, Burnmouth Bridge continues to meet the criteria for listing. The statutory address for this bridge was incorrectly listed as 'Pitcarity Bridge' in 1971. The statutory listing address has been amended.

Previous Statutory Address	Pitcarity Bridge over Burn of Inchmill
Amended Statutory Address	Burnmouth Bridge over Burn of Inchmill

2. Designation Background and Development Proposals

2.1 Designation Background

This bridge was listed at category B in 1971.

2.2 Development Proposals

There are no known development proposals.

3. Assessment

3.1 Assessment information

Burnmouth Bridge was given the incorrect name when it was listed in 1971.

Burnmouth Bridge has not been visited. The present assessment is desk-based, using available information and has included reference to recent photographs.

3.2 Assessment against designation criteria

An assessment against the listing criteria was not carried out.

The designation criteria are published in the Historic Environment Scotland policy statement June 2016, Annex 2, pp. 51-53.

<https://www.historicenvironment.scot/advice-and-support/planning-and-guidance/legislation-and-guidance/historic-environment-scotland-policy-statement/>

Elizabeth McCrone

Head of Designations
Heritage Management
Historic Environment Scotland

Contact	Yvonne Hillyard, Designations Officer Yvonne.hillyard@hes.scot, 0131 668 8088
----------------	--