

Corgarff Castle Reharling of outer wall



Corgarff Castle from the North showing the hall to reharl and renew copes

Corgarff Castle Reharling of outer wall



Renewal of lime harl to south outer wall in progress 2010

Corgarff Castle Reharling of outer wall



New copes being placed to south wall 2010

Corgarff Castle Reharling of outer wall



The failing harl to the north wall before its removal in 2011, note delaminating old copes.

Corgarff Castle Reharling of outer wall



The failing harl to the north wall before its removal in 2011, note delaminating old copes.